

G HOME™ PERFORMANCE REPORT

G Home™ by G STREET

**3313 E Medlock Drive
Phoenix, AZ**



Energy

HERS Index

65

pre-HERS Index

232

Monthly Energy Costs

\$110

Annual Energy Savings

\$1700

Above numbers are estimates and are partly based on Occupant behavior

Water

Estimated Gallons Saved Resulting From Improvements

265,000

Water Savings

61%

Estimates are base on improvements and Occupant behavior and are not guaranteed

Location

100
BEST

Somewhat Walkable

66

0
WORST

Walk Score calculates the walkability of any address and helps find walkable places to live. A score of "Very Walkable" means most errands can be accomplished on foot.

www.walkscore.com

Indoor Air Quality

Professionally Designed Mechanical System

Brand New Duct System Sealed Ducts During Construction

MERV 8 Filters

Updated Ventilation System with improved CFM

Low-VOC Materials

Plant Based Solutions used during Final Clean

ENERGY

14 SEER HVAC (split system)

Conditioned Attic

5.5" Icynene Foam Insulation in all Exterior Surfaces

Tyvek Wrap

Low-E Windows

ENERGY STAR Appliances

Marathon High Performance Water Heater

WaterSense Fixtures

Lighting per 2012 IECC

WATER

Professionally Designed, Non-invasive Landscape

Drip Irrigation

Irrigation Timer

WaterSense Fixtures

Low Flush Toilets

AIR

low-VOC Paint and Finishes

Professionally Designed Mechanical System

Fresh Air Intakes

MERV 8 Filters

Improved Ventilation in all WC's

CRI+ Padding

Wool Carpet

DESIGN

Landscape Architect Mary Estes

ASID Interior Designer ab Design Elements

Mechanical Design REEis

NAHB Verifier Shawn Mullins

Meeting Conducted Prior to Construction Pre-Design

Pre-Design Meeting Conducted Prior to Construction



G Street™ | info@gstreetinc.com | 855.466.7444 | gstreetinc.com

©2012 G Street™. All rights reserved. G Street™ and the G Home™ Performance Report are registered trademarks of G STREET™